

Plas Madoc Site Plan- Gwynant

Plas Madoc Site Plan- Gwynant

El Sub Sta

Play
Area



Accommodation Schedule

04 No. 182P	
02 No. 284P	
02 No. 384P	
03 No. 486P	
11 No. Total	

Boundary Treatments

Rear Boundaries - Vertical featherboard panels as Employer's Requirements

Front Boundaries - Metal Railing Style

University Helsinki Checklist		
Criterion	Area of residence	
1	Accession from parking	✓
2	Approach to entrance	✓
3	Entrances	✓
4	Entrances from parking and stairs	✓
5	Internal security and fire alarms	✓
6	Evacuation routes	✓
7	Entrance from parking	✓
8	Entrance level indicators	✓
9	Entrance level not used	✓
10	Internal security and fire alarms	✓
11	Internal security and fire alarms	✓
12	Internal security and fire alarms	✓
13	Internal security and fire alarms	✓
14	Internal security and fire alarms	✓
15	Internal security and fire alarms	✓
16	Internal security and fire alarms	✓

Developers' Quality Requirement Checklist		
Criterion	Area of residence	
1	Accession from parking	✓
2	Approach to entrance	✓
3	Entrances	✓
4	Entrances from parking and stairs	✓
5	Internal security and fire alarms	✓
6	Evacuation routes	✓
7	Entrance from parking	✓
8	Entrance level indicators	✓
9	Entrance level not used	✓
10	Internal security and fire alarms	✓
11	Internal security and fire alarms	✓
12	Internal security and fire alarms	✓
13	Internal security and fire alarms	✓
14	Internal security and fire alarms	✓
15	Internal security and fire alarms	✓
16	Internal security and fire alarms	✓

A	4th o. Bed layout amended for 11kW outseam(1)	05.03.19	RT
---	--	----------	----

C	D	S	G	Contract Construction
			J	As Built
I	I	Bidding Begins	L	Sketch
I	I	Issued	S*	

| dd architects

introduction@clifford.com

www.dunarchitects.com

Phone: (761) 335-5011

Accepted: 2007/06/14

FO

Gwynant & G...

W

Grade:	U.S. 4	State:
U.S. 4	U.S. 4	U.S. 4

Aug	CV	MC
-----	----	----

1000

1045	A	101	Proper
------	---	-----	--------

[illegible]

10